

BOEING 747 No. 1, 2 & 3

Glass Cockpit Windows

New Spares / Overhaul / Exchange Program

History

The replacement of cockpit windows due to delamination, glass breakage and electrical failures is costly in both aircraft downtime and increased maintenance expense. Until recently, only minor repair of glass side cockpit windows was available to 747 operators.

Solution

GKN Aerospace Transparency Systems is an OE manufacturer of Boeing 747 cockpit windows. In addition to the licensed sale of new No. 1 windshields and side cockpit windows, GKN offers a comprehensive factory repair and overhaul to restore unserviceable No. 2 & No. 3 windows to “as-new” condition for longer service life.

Overhaul Features

- Overhaul to latest OE specifications including new replacement components
- Replacement of broken glass, defective heating systems and/or delaminated components
- Purchase of Unserviceable Scrap Windows
- Exchange Pool Available
- *Surfex 100™* Rain Shed Coating Upgrade Option
- OE Licensed Repair
- FAA Approved* - Full Airworthiness Certification
- Warranty - 36 months - the same as a new window!
(See back for complete details)

Part Numbers

Boeing	GKN ATS	Part Description
60B10028-17	06372	<i>Left Hand No. 1</i>
60B10028-18	06373	<i>Right Hand No.1</i>
65B27042-1	06304	<i>Left Hand No. 2</i>
65B27042-2	06305	<i>Right Hand No. 2</i>
65B27043-1	06306	<i>Left Hand No. 3</i>
65B27043-2	06307	<i>Right Hand No. 3</i>

The above part numbers are for GKN ATS manufactured windows only.

WARRANTY

GENERAL WARRANTY

Seller warrants that at the time of delivery the articles furnished hereunder will be free from defects in material and workmanship and will conform to the drawings and specifications. Except for latent defects, all articles furnished hereunder shall be deemed to be finally accepted by Buyer unless Seller receives notice of rejection within a reasonable time but no later than 90 days after the receipt of articles by Buyer. As to latent defects, Buyer may reject articles within three years after date of shipment. If Seller elects to repair or replace a defective or non-conforming article, Seller's warranty for said article shall be limited to the unused portion of the original warranty. ***THERE ARE NO WARRANTIES WHICH EXTEND BEYOND THE DESCRIPTION ON THE FACE HEREOF.***

WARRANTY PROVISION

There shall be no Continuing Warranty by Seller for defects attributable in whole or in part to normal wear and tear or to factors beyond Seller's control, including but not limited to Buyer's design, failure of Buyer or its customers to properly preserve, store, install, operate, or maintain parts made by Seller or the end item in which parts are installed. Seller also denies liability for any failure or deterioration of parts attributable to extended storage under conditions of excessive temperature or humidity, or for any malfunction or design deficiency occurring in other systems or installations that would in turn affect the performance of the part. Seller further denies liability for performance of parts under the Continuing Warranty provision where abnormal environmental and/or operating conditions are encountered by the aircraft (or Buyer's end item).

SELLER'S LIABILITY

Seller's liability for defective or nonconforming articles is limited to the repair or replacement with surface freight shipping charges in the Continental United States to be paid by Seller, or refund of the purchase price as Seller may elect. Defective or nonconforming articles shall not be returned to Seller without Seller's prior written permission. Under no circumstances shall Seller be obligated for consequential, incidental or other damages, losses or expenses in connection with or by reason of any breach. Seller's liability hereunder shall in any event be limited to the purchase price of the articles. The remedies expressed are exclusive. Claims for defective or nonconforming articles shall be in writing and submitted within the period specified in the General Warranty.

Please contact us at the numbers below for further information or for other available repair programs.



12122 Western Ave.
Garden Grove, CA 92841
Tel.: 714.893.7531
Fax: 714.892.7635
SITA SNAPAXD

Eckersall Road, Kings Norton
Birmingham, B38 8SR England
Tel.: 44.121.606.4100
Fax: 44.121.606.4191
ARINC: BHPXZXD

9/21 Moo 5, Phaholyothin Road
Klong 1, Klong Luang,
Patumthanee, Thailand 12120
Tel.: 66.2.516.1058
Fax: 66.2.902.0414

Avenida Central, 211 - Chácaras
Reunidas, CEP 12238-430
São José dos Campos, SP-Brazil
Tel.: 55.012.3934.3418
Fax: 55.012.3931.9006

London Luton Airport
Luton Bedfordshire
LU2 9PQ, United Kingdom
Tel.: +44 (0) 1582.731441
Fax: + 44 (0) 1582.452049