

CESSNA CARAVAN MODEL 208

Windshield Anti-Ice



Before

After

HISTORY

Anti-Ice panels may become unserviceable due to wire heating element burnout and breakage, delamination, and glass ply breakage.

SOLUTION

GKN Aerospace Transparency Systems offers comprehensive overhaul which replaces the damaged glass laminate and restores the panel to an “as new” condition.

OVERHAUL FEATURES

- *FAA Approved – Full Airworthiness Certification*
- *Replacement of damaged glass and heating element*
- *Overhaul and refurbishment of window frame*
- *Replacement or salvage of minor components*
- *Full restoration to new finishes and tolerances*
- *Application of anti-static coating to outer surface*
- *Installation of ground wire for static drain*

Windshield Anti-Ice Panel

Overhaul / Exchange

APPLICATION

Cessna Caravan aircraft models 208, 208A and 208B

REPAIRABLE PART NUMBERS

Cessna P/N's 2601058-1, 2601058-3, and 2601445-1

These assemblies may be more readily identified by the label on the inboard, lower left corner of the glass panel (PPG P/N NP165511).

REPAIR CRITERIA

The window frame must be structurally sound and within repairable limits. Damage to the glass laminate assembly is not limited, as these components will usually be replaced.

UPGRADE OPTIONS

Panels may be upgraded to the latest configuration which uses a spring-rod assembly in place of the elastic lanyard mechanism to secure the anti-ice panel to the windshield.

DELIVERY

Standard lead-time is 30 days from time of receipt.
Exchange lead-time is 7 days, subject to availability.

WARRANTY

One (1) year warranty from date of delivery. Subject to term and conditions of GKN Aerospace Transparency Warranty and Liability Provisions.

PRICING

Quoted Upon Request. Please contact Sam Lee at :
Phone : (714) 893-7531 Ext. 229
Fax: (714) 892-7635
Email: Sam.Lee@tsus.aero.gknplc.com



12122 Western Ave.
Garden Grove, CA 92841
Tel.: 714.893.7531
Fax: 714.892.7635
SITA SNAPAXD

Eckersall Road, Kings Norton
Birmingham, B38 8SR England
Tel.: 44.121.606.4100
Fax: 44.121.606.4191
ARINC: BHPXZD

9/21 Moo 5, Phaholyothin Road
Klong 1, Klong Luang,
Patumthanee, Thailand 12120
Tel.: 66.2.516.1058
Fax: 66.2.902.0414

Avenida Central, 211 - Chácaras
Reunidas, CEP 12238-430
São José dos Campos, SP-Brazil
Tel.: 55.012.3934.3418
Fax: 55.012.3931.9006

London Luton Airport
Luton Bedfordshire
LU2 9PQ, United Kingdom
Tel.: +44 (0) 1582.731441
Fax: + 44 (0) 1582.452049